

Appendix C

Photologs



Figure 1: Westfield NJ, July 2019, Borehole Site 2. Inundation



Figure 2: Westfield NJ, July 2019, Borehole Site 2. Landscape



Figure 3: Westfield NJ, July 2019, Borehole Site 2. Buttressed Tree Trunk



Figure 4: Westfield NJ, July 2019, Borehole Site 3. *Carex lurida wahlen sedge*, OBL



Figure 5: Westfield NJ, July 2019, Borehole Site 3. *Carex lurida* wahlen sedge, OBL



Figure 6: Westfield NJ, July 2019, Borehole Site 3. Buttressed Tree Trunk